

Rotary Reads Kids Club RFP Answers to Questions #2

Questions Received as of April 16, 2018

Question period closed on April 16, 2018

Question: Can you tell us which branches currently have lead or asbestos (confirmed or suspected) that if confirmed positive will require abatement as part of these renovation projects?

Answer: The RFP states that all work will be cosmetic only. No changes to existing physical wall/ceiling/floor structures can occur. Be aware that the Frank E. Merriweather, Jr. Branch Library, which opened in 2005, does not have asbestos or lead paint. Due to the age of the other buildings, asbestos and/or lead paint are present at some of these libraries.

Should the design concept require mounting or hanging, the Library Maintenance Department will help facilitate by providing the needed support and guidance as to what will be allowed and required.

Question: Can you provide square footage and/or layouts for these branches, where dimensions or layouts were not provided to date:


- Frank E. Merriweather, Jr Library
- Niagara Branch Library (layout provided but no dimensions)
- North Park Branch Library

Answer: Layouts with limited dimension information for the Niagara and Merriweather Libraries are attached.

Square footage for the North Park Library (all one floor slab foundation) is approximately 5,662 square feet. This expansion was completed in 2017.


Designers are welcome to visit the libraries during normal business hours to see first-hand the current design and layout of the children's spaces. Photos may be taken. However, the photographing of individuals inside the libraries is strictly prohibited.

Proposals must be submitted no later than May 2, 2018 by 2 pm eastern time per RFP Instructions.



MERRIWEATHER BRANCH LIBRARY
 1324 JEFFERSON AVE
 1st FLOOR

* The Children's Area of the Merriweather Branch is 57'-6" across.



Niagara
Branch
Library
1st flr

62'
N

104'

47'-3"

Office

Closet

Kit

Storage

DWN

DWN